

To accompany Notice to Mariners 5715/17

On Chart 2710

SUBMARINE PIPELINES AND CABLES
Additional uncharted submarine pipelines and submarine cables may exist within the area of this chart. Not all submarine pipelines and submarine cables are required to be buried, and those that were originally buried may have become exposed. Mariners should use extreme caution when operating vessels in depths of water comparable to their draft in areas where pipelines and cables may exist, and when anchoring, dragging, or trawling.

To accompany Notice to Mariners 5715/17

On Chart 2861

SUBMARINE PIPELINES AND CABLES
Additional uncharted submarine pipelines and submarine cables may exist within the area of this chart. Not all submarine pipelines and submarine cables are required to be buried, and those that were originally buried may have become exposed. Mariners should use extreme caution when operating vessels in depths of water comparable to their draft in areas where pipelines and cables may exist, and when anchoring, dragging, or trawling.

To accompany Notice to Mariners 5715/17

On Chart 4403

SUBMARINE PIPELINES AND CABLES
Additional uncharted submarine pipelines and submarine cables may exist within the area of this chart. Not all submarine pipelines and submarine cables are required to be buried, and those that were originally buried may have become exposed. Mariners should use extreme caution when operating vessels in depths of water comparable to their draft in areas where pipelines and cables may exist, and when anchoring, dragging, or trawling.

To accompany Notice to Mariners 5786/17

On Chart 1426

SUBMARINE CABLES AND PIPELINES
Mariners are advised not to anchor or trawl in the vicinity of submarine cables and pipelines.

To accompany Notice to Mariners 5806/17

On Chart 1020

AREA TO BE AVOIDED
(8° 38'·1N., 83° 46'·6W.)
To avoid the risk of pollution and damage to the environment, this area has been designated an Area to be Avoided. All vessels of 900GT and over should avoid this area. This area is IMO-adopted.

To accompany Notice to Mariners 5806/17

On Chart 1021

AREA TO BE AVOIDED
(8° 38'·5N., 83° 46'·6W.)
To avoid the risk of pollution and damage to the environment, this area has been designated an Area to be Avoided. All vessels of 900GT and over should avoid this area. This area is IMO-adopted.

To accompany Notice to Mariners 5806/17

On Chart 2493

AREA TO BE AVOIDED
(8° 25'·00N., 83° 15'·00W.)
To avoid the risk of pollution and damage to the environment, this area has been designated an Area to be Avoided. All vessels of 900GT and over should avoid this area. This area is IMO-adopted.